

Kansas Historic Resources Inventory

Printed: 08/09/2016



139-0000-00002
WD Harris Barn
Address restricted.
Four Corners vicinity



LOCATION:

County: Osage

Address:

Address Remarks: Address restricted.

City: Four Corners vicinity

Zip: 66537

Parcel ID:

Legal Description: SE 1/4 of Section 1 Township 15S Range 15E

Legal Description Remarks:

Latitude, Longitude 1:

Latitude, Longitude 2:

Latitude, Longitude 3:

Latitude, Longitude 4:

Datum: WGS84

DESCRIPTION:

Historic Name: WD Harris Barn

Alternate Name: 110 Mile Barn

Historic Function: Agriculture/Subsistence

Subcategory: Animal Facility

Historic Function Remarks: 1970s surveys: Structure located at McGee's Crossing on 110 Mile Creek. Rectangular barn. Used as hotel and store until railroad built. Original lime plaster cement between stones. Not used for last 10 years or longer. Believed to have been hotel and store for travelers until converted to barn. [07/27/71]
Additional articles available on file with SHPO.
[also surveyed 08/10/73 by David Ramsey Wilson, under the same inventory number]

Present Function: Vacant/Not in Use

Subcategory:

Present Function Remarks:

Residential/Commercial/Religious Style:

Secondary Style:

Barn Type: Vernacular

Bridge Type: Not Applicable

Landscape Type:

Physical Description/Remarks: Frame additions and alterations.

Plan Form: Rectangle
Commercial Building Type: Not Applicable
Roof Form: Gable
Stories: 2
Condition: Ruins
Principal Material: Stone
Condition Remarks: wood shingle roof
Architect/Designer/Builder: Harris, William D.
Year of Construction: 1860
Certainty: Estimated
Date Notes:
General Remarks:
Ancillary Structures:
Ancillary Structure Remarks:

REGISTER STATUS:

Listed in State Register: No
Date of State Listing:
Listed in National Register: No
Date of National Listing:
Historic District:
Demolished:
Date Demolished (if applicable):
Potentially Eligible for National Register: Contributing
Register Status Remarks:
Thematic Nomination (MPDF):
National Historic Landmark:

SURVEY INFORMATION:

Survey 1
Survey Project Name: Kansas - Santa Fe Trail Survey (2011-2012)
Sequence Number: OS01b
Surveyed By: KSHS/Hoard, Bob
Survey Date: 08/09/2012

IMAGES & DOCUMENTS



Harris Barn. From NE. 07/27/1971.



Harris Barn. From NW. 07/27/1971.



Harris Barn. From NW. 07/27/1971.



McGee's Crossing. Article from Overbrook Citizen. 05/11/1961.



McGee's Crossing. Article from Overbrook Citizen. 05/11/1961.



McGee's Crossing. Article from Osage County Chronicle. 10/02/1913.



McGee's Crossing. Article from Osage County Chronicle. 10/02/1913.



Barn. Looking S at barn ruins. 07/1991. URBANA/Hamilton.



Barn. Looking N at barn ruins. 07/1991. URBANA/Hamilton.



Barn. Looking N at barn ruins. 07/1991. URBANA/Hamilton.



Barn. View to west, looking at east wall. 08/09/2012. KSHS/Hoard, Bob.



Barn. Interior view to west, showing west wall. 08/09/2012. KSHS/Hoard, Bob.



Barn. View to south. 08/09/2012. KSHS/Hoard, Bob.



Barn. Elevation, west wall. 08/09/2012. KSHS/Hoard, Bob.



Barn. View to northeast of west wall. 08/09/2012. KSHS/Hoard, Bob.



Barn. West wall, window detail.
08/09/2012. KSHS/Hoard, Bob.



Barn. View to northeast. Station lies
further east, hidden in treeline.
08/09/2012. KSHS/Hoard, Bob.